


Work Surface Assembly



The Small Work Surface will be assembled first.


Locate the following parts:

- 1 pc. E1 L.H. Tilt Slide
- 1 pc. E2 L.H. Work Board Side
- 1 pc. E3 Small Work Board
- 1 pc. E4 R.H. Work Board Side
- 1 pc. E5 R.H. Tilt Slide
- 1 bag E11 hardware



Place E3 Small Work Board on top of (2) F1 Equipment Bars.

Position Small Work Surface Parts in numerical order, from E1 to E5 as shown.



Insert Screw from E11 hardware bag, with (1) washer under its head into the hole in E1 through the hole in E2, and into the hole in E3. Wax screw prior to insertion.